

LHM01	
Structure	OK (Structural Repairs executed on the crane based on Inspections findings) OBS: installed escape route ladder
Engine	Engine replaced (2016)
Transmission	PTO replaced (2017)
Hydraulics	Motor Hydraulic replaced (2017)
Hoist/ropes/sheaves	Ropes replaced (2018)
Lighting	Revise support; review access lighting
Boom/luffing system	OK (Structural Repairs executed on the crane based on Inspections findings)
Slewing system	OK
Electrical	review camera system, electric boom cable, generator module, electric panels, electric motor cable and electric valve cables.
Undercarriage	lower cabin without HMI; three cylinder leaking, spare unit available
Outriggers	OK